

LOCKOUT PROCEDURE

**CEM Machine & Carpentry Shops
College of Engineering & Mines
Duckering 109-110**

PURPOSE:

This procedure establishes the minimum requirement for the lockout of energy isolating devices whenever maintenance or servicing is done on machines or equipment. It shall be used to ensure that the machine or equipment is stopped, isolated from all potentially hazardous energy sources

which the exclusive control of the plug cannot be m

6) Reenergize the equipment or machine.